2. USE

DESCRIPTION OF THE DISPLAY

AVS : Average speed (maxi 99.9)

M : Miles

KM : Kilometers

MXS : Maximum speed (maxi 99.9)

▲▼ : Speed comparison

ATM : Stopwatch

ODO : Cumulative odometer (up to 99 999)

CAD : Pedaling cadence (up to 180) (optional)

DST : Daily distance (9 999.9)

CLK : Time

DISPLAY OF FUNCTIONS

Left button :

1. Stopwatch and average speed

2. Cumulative odometer and maximum speed



Right button :

1. Daily distance and current speed

2. Current time and speed

3. Cadence (optional) and current speed



Standby mode

After **30 mn** of inactivity, the display turns off to save the battery. To get out of the standby mode, simply press one of the 2 buttons on the computer : the screen turns on automatically and the computer is ready to receive information again and display it.

RESETTING THE DAILY FUNCTIONS TO 0

(daily distance, stopwatch, average and maximum speed)

Starting from any screen, press the 2 buttons at the same time for 2 seconds.