


WIN-Tech® FS

USE: Use only on a Cross Country or Cross Mountain MTB, a road bike, a tandem or an Asphalt type of bike. Any other use (such as on an Extreme MTB, Cyclo-Cross bike...) is strongly inadvisable, is the sole responsibility of the user and voids the Mavic warranty.

WEIGHT:
Computer: 46 g
Computer bracket: 8 g
Fork sensor: 18 g

REFERENCES:
WIN-Tech FS: 323 687 01
WIN-Tech FS + cadence: 323 932 01

SPARE PARTS



MAINTENANCE: Clean with dry cloth or soap and water. Do not use pressurized water.
Do not store near a window exposed to the sun for a long period of time.

REFERENCES OF ACCESSORIES

Fixing ties: M40390, pack of 50 ties
Wheel magnet bracket: M40540
Computer bracket kit: 323 511 01 (includes the bracket, double-sided tape, orientation wedge and 3 fixing ties)

FUNCTIONING FEATURES

Power supply: battery CR2032 (Computer, speed sensor)
Circumference: minimum: 180 cm, maximum: 229 cm.
Unit: distance and speed in miles or kilometers
Time format: 24 H
Water resistance: Resistant to rainwater. Avoid total immersion of the electronic components and do not use pressurized water.
Maximum transmission distance: 60 cm

Operating temperature range: -10 to + 50°C / 14 to 122°F
Cumulative odometer: up to 99,999 km or m
Trip distance: up to 9,999.9 km or m
Stopwatch: up to 9:59:59
Speed: up to 99.9 km/h or m/h
Cadence: up to 180 revs / min

INSTALLATION, USE AND PROGRAMMING

• **Installing the computer** See 2004 technical manual, page 42
• **Installing the speed sensor** See page 41
• **Installing the magnet bracket** See page 41
• **Installing the batteries** See 2004 technical manual, page 43

• **Use** See 2004 technical manual, page 44
• **Programming** See 2004 technical manual, pages 44 to 45
• **Digital synchronization** See page 42